
Sig

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	Gener	neral Information			
	1.	Report Time Period: From (mo./yr.) Jan - 93 To (mo./yr.) Dec - 93			
	2.	DOGM File Number (Mine No): M / 027 / 006			
	3.	Mine Name: Cricket Mountain			
	4.	Mineral(s) Mined (or permitted to mine): Limestone			
	5.	Type of mine			
	6.	Legal Description (Location of Lands Affected):			
		SW 1/4, SE 1/4, Section 25 , Township T21S , Range R10W			
		SE 1/4, SW 1/4, Section 25 , Township T21S , Range R10W			
		N 1/2, Section 36 , Township T21s , Range R10W			
	7.	Name of Operator or Company:Continental Lime Inc.			
	8.	Permanent Street Address: P.O. BOX 669			
		City, State, Zip: Delta, Utah 84624			
		Phone: (801) 864-3823			
	9.	Company Representative (or designated operator):			
		Name: Russell Dobson			
		Title: Plant Manager			
		Business Address: P.O. Box 669			
		City, State, Zip: Delta, Utah 84624			
		Phone: (801) 864-3823			
		Please check if any of the above information has changed since previous year.			
II.	Minin	Mining and Reclamation			
	1.	Was the mine active during the past year? Yes ☒ No ☐			
	2.	If active, how much ore or mineral was mined? 961,000 tons			

	3.	How much additional acreage	was disturbed during the past year?	
	4.		dditional surface disturbances that occurred scription should include the type of work terial moved.	
		Topsoil removal, waste s	tripping, and Limestone minning occurred	
		between the 6000 and 594	elevations on east flank of the south	
		extension in the Poison	mountain Quarry.	
5.	5. How much acreage was reclaimed during the past year?0			
6. Briefly describe the reclamation work performed during the particle description should include methods employed, and an evaluate results.			ls employed, and an evaluation of the	
		None performed	<u> </u>	
7.	What is the total disturbed acreage at years end?			
8. Briefly summarize any mining and/or reclamation plans for the upcoming year.				
		Waste stripping and Limst	one minning from the 5960, 5940, and 5920	
		benches will total 1.7 million tons. Reclamation of 5960 bench		
		and possibly the 5940 ber	ch will be completed in 1994.	
NOTE:		Section III., "Additional Informatio	on" applies only to <u>large mining operations</u> .	
III. Additio	nal	Information		
1.		An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.		
2.		Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.		
IV. <u>Signat</u> ı	ure	<u>Requirement</u>		
I he	ereb	y certify that the foregoing is true	e and correct.	
		Name (Typed or Print):	Russell Dobson	
	•	Title of Operator:	Plant Manager	
		Signature of Operator:	Therepalon	
		Date:	Jan 21 1994	